

Keenan, John

From: Nicholson, Albert (Al) <anicholson@omakwood.com>
Sent: Wednesday, November 27, 2013 9:04 AM
To: kris.ray@colvilletribes.com; Chaney, Connie
Cc: Olson, Gary; Keenan, John; gary.passmore@colvilletribes.com
Subject: RE: O2 Analyzer

It is mostly due to the inversion here in the valley. We are not doing anything different. I asked Connie early This morning to read and document the smoke coming out of the stack.

Regards,

Al Nicholson

From: Kris Ray [<mailto:Kris.Ray@colvilletribes.com>]
Sent: Wednesday, November 27, 2013 8:18 AM
To: Chaney, Connie
Cc: Gary Olson; keenan.john@epa.gov; Nicholson, Albert (Al); Gary Passmore
Subject: Re: O2 Analyzer

Why is the mill emitting a very high quantity of smoke
Sent from my iPhone

On Nov 27, 2013, at 7:55 AM, "Chaney, Connie" <cchaney@omakwood.com> wrote:

Hi Gary,

Due to circumstances beyond our control, we will not be able to install the O2 analyzer as scheduled. We will make arrangements, when the availability and cooperation with receiving the parts, to install as soon as possible. Any questions, please don't hesitate to call me at (509)322-7348.

Thank you for your understanding and patience.

Connie Chaney
Omak Wood Products
Environmental Mngr